

# INSPECTION REPORT (検品書)

SERIAL NUMBER (号機) : <b>L32-3-S33-02297</b>	29516 HR
ENGINE NO. (エンジン号機) : <b>6HK1-510268</b>	YR
EMISSION REGULATION (排ガス規制) : <b>TIER 2 EMISSION STANDARDS 2次排ガス</b>	km
Tire Size (タイヤサイズ) : <b>23.5 - 25 16PR</b>	EPA: WITH / <del>WITHOUT</del>

項目	評価	メモ	項目	評価	メモ
<b>ENGINE エンジン</b>			<b>TIRE タイヤ</b>		
Main Engine <エンジン本体>	C		Front Right Tire <右前輪>	C	
Head Cover <ヘッドカバー>	C		Front Left Tire <左前輪>	C	
Sound <音>	C		Rear Right Tire <右後輪>	C	
Exhaust Pressure <排圧>	C		Rear Left Tire <左後輪>	C	
Exhaust Color <排気色>	C		<b>OUT LOOKING 外観</b>		
Muffler Body <マフラー本体>	C		Bucket <バケット>	C	
Radiator <ラジエター>	C		Lift Arm <リフトアーム>	C	
Oil Cooler <オイルクーラー>	C		Looseness of center pin <センターピンガタ>	C	
<b>MAIN PUMP ポンプ</b>			Front Axle <フロントアクスル>	C	
Oil Leaking <オイル漏れ>	C		Rear Axle <リアアクスル>	C	
Sound <音>	C		Wheel Rim <ホイールリム>	C	
Power <パワー>	C		Frame <フレーム>	C	
Contol Valve <コントロールバルブ>	C		Tanks&Covers <タンク・カバー類>	C	
Hose/Pipe etc. <ホース/配管類>	C		Mud Guard <フェンダー類>	C	DENT へこみ
<b>OPERATION SYSTEM 操縦関係</b>			Step <ステップ>	C	
Running <走行>	C		Paint <塗装>	C	
Main Clutch / Torque Converter <メインクラッチ/トルコン>	C		<b>HYD.CYLINDER シリンダー関係</b>		
Transmission <トランスミッション>	C		Lift Cylinder <リフトシリンダー>	C	
Propeller Shaft <プロペラシャフト>	C		Dump Cylinder <ダンプシリンダー>	C	
Steering / Power Steering <ステアリング/ パワステ>	C		Steering Cylinder <ステアリングシリンダー>	C	
Brake <ブレーキ>	C		<b>OTHER 付属部品</b>		
<b>INTERIOR キャビン内装</b>			Battery <バッテリー>	GOOD / FLAT	
Cabin Appearance <キャビン外観>	C		Ride Control System <ライドコントロール>	WITH / <del>WITHOUT</del>	
Glass <ガラス>	D	CRACK 亀裂	AUTOMATIC CHANGING GEAR TROUBLE 自動変速不良		
Operator Seat <シート>	C	RIPPED 破れ			
Floor Mat <フロアマット>	C				
Monitor <モニター>	D	4 SPEEDS BLINKING ALWAYS 常に4速点滅			
Air-Cond. <エアコン>	D	BROKEN 故障			
Operation Lever <操作レバー>	C				
Pedal <ペダル>	C				

A: replaced with brand new or rebuilt parts B: in good working condition considering its age C: normal operation; appears worn and deterioration  
D: operational, but need repairs E: need quick repairs or replacement parts  
A: 新品または再生品 B: 経年に比例して良好 C: 稼働に異常は無いが経年相当の摩耗・劣化あり  
D: 稼働はするが修理が必要 E: 即修理をしないと稼働しない

\*We described this inspection report based on our judgement and view. We do not guarantee the condition shown on this inspection report.  
\*この検品書は私どもの見解判断に基づいて作成したものであり、機械の程度を保証するものではありません。